I	3
F	?
I	

AD

SPECIAL PUBLICATION BRL-SP-46

RACK FOR TEMPORARY STORAGE OF 105 MM HEAT AMMUNITION

Philip M. Howe

March 1985

APPROVED FOR PUBLIC RELEASE; DISTRIBUTION UNLIMITED.

US ARMY BALLISTIC RESEARCH LABORATORY ABERDEEN PROVING GROUND, MARYLAND

Destroy this report when it is no longer needed. Do not return it to the originator.

Additional copies of this report may be obtained from the National Technical Information Service, U. S. Department of Commerce, Springfield, Virginia 22161.

The findings in this report are not to be construed as an official Department of the Army position, unless so designated by other authorized documents.

The use of trade names or manufacturers' names in this report does not constitute indorsement of any commercial product.

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE	READ INSTRUCTIONS BEFORE COMPLETING FORM					
1. REPORT NUMBER 2. GOVT ACCESSION NO. SPECIAL PUBLICATION BRL-SP-46	3. RECIPIENT'S CATALOG NUMBER					
4. TITLE (and Subtitle)	5. TYPE OF REPORT & PERIOD COVERED					
RACK FOR TEMPORARY STORAGE OF 105 MM HEAT AMMUNITION	6. PERFORMING ORG. REPORT NUMBER					
7. AUTHOR(a)	8. CONTRACT OR GRANT NUMBER(s)					
PHILIP M. HOWE						
9. PERFORMING ORGANIZATION NAME AND ADDRESS US Army Ballistic Research Laboratory ATTN: AMXBR-TBD	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS					
Aberdeen Proving Ground, MD 21005-5066	1L162618AH80					
11. CONTROLLING OFFICE NAME AND ADDRESS	12. REPORT DATE					
US Army Ballistic Research Laboratory	March 1985					
ATTN: AMXBR-OD-ST	13. NUMBER OF PAGES					
Aberdeen Proving Ground, MD 21005-5066 14. MONITORING AGENCY NAME & ADDRESS(II different from Controlling Office)	11 15. SECURITY CLASS. (of this report)					
14. MONITORING NOCIOTI NAME & ABBRESSIN SINSSIN INSER SUMMINING SINSSIN	or allowing allowed the second					
	UNCLASSIFIED 15a. DECLASSIFICATION/DOWNGRADING SCHEDULE					
16. DISTRIBUTION STATEMENT (of this Report)	L					
Approved for public release; distribution is unlimited.						
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different fro.	m Report)					
18. SUPPLEMENTARY NOTES						
'						
19. KEY WORDS (Continue on reverse side if necessary and identify by block number)						
ammunition storage explosives safety distance 105 mm ammunition						
20. ABSTRACT (Continue on reverse side if necessary and identify by block number)						
This special publication describes the construction temporary storage of 105 mm tank ammunition in densistent with explosive safety criteria. The rack, barricaded, reduces the blast distance for inhabite hazardous fragment distance to 50 feet. Approval through channels, from the DOD Explosives Safety Be this document be used for construction guidance and	sely populated areas, con- when properly fabricated and ed buildings and the for siting must be obtained, oard. It is intended that					

DD 1 JAN 73 1473 EDITION OF 1 NOV 65 IS OBSOLETE

equired for site approval

I. INTRODUCTION

The purpose of this report is to outline requirements for construction of a rack which can be used for temporary storage of M456 heat ammunition and other 105 mm tank ammunition in congested areas, consistent with DOD explosives safety criteria.

II. BACKGROUND

Reference is made to DOD 6055.9STD, DOD Ammunition and Explosives Safety Standards ¹ and AR 385-64, Ammunition and Explosive Safety Standards, ² which implements the Department of Defense Standards. Reference is also made to Ballistic Research Laboratory Memorandum Report entitled "Temporary Tank Ammunition Storage Facility" ³ (in press).

Quantity-distance (Q-D) criteria for storage of conventional ammunition are designed to provide an appropriate level of protection against blast and fragment hazards. Explosives safety distance tables prescribe necessary separations and specify maximum quantities of the various classes of explosives permitted in any one location. These tables reflect acceptable minimum criteria for storage and handling of explosives. Such criteria provide reasonable safety within specified limits compatible with the risks of accidental explosion. Both the DOD 6055.9STD and the AR which implements this standard for Army installations and activities provide the opportunity for reduced hazard distances corresponding to reduced fragment and blast hazards, if it can indeed be demonstrated that the hazards are reduced. The burden of proof is upon the initiating activity to demonstrate an acceptable level of safety, however.

III. RATIONALE

The design of this storage rack was predicated upon the assumption that the rack should control explosion size, thus limiting the maximum credible event to some small fraction of the total stores, and should also contol fragment hazards. The rack specified herein limits the maximum credible event to explosion or detonation of one warhead, with a corresponding blast radius (inhabited building distance) of 50 feet. With a 6 inch sand cover (as provided by one layer of sandbags), on the sides and roof, and with front and rear barricades, primary fragments are contained completely, kickouts are reduced to a minimum, and the fragment hazard radius, based upon one hazardous fragment per 600 square feet, is also less than 50 feet. Thus, when 105 mm M456 HEAT ammunition and other nonexplosive conventional antitank ammunition are stored, in their fiber shipping tubes, in the rack, warheads facing to the rear of the rack, the appropriate hazard distance is 50 feet, regardless of the total number of rounds stored at one site.

DOD 6055.9STD, DOD Ammunition and Explosives Safety Standards, July 1984.

 $^{^2}$ AR 385-64, Ammunition and Explosive Safety Standards.

Philip M. Howe and David L. Collis, "Temporary Tank Ammunition Storage Facility," BRL-MR-3424 (in press).

IV. RACK DESCRIPTION

A shop drawing of the rack is shown in Figure 1. The rack consists of a steel frame made of angle iron, welded or bolted together, and steel spacer rods welded or bolted in position to hold the fiber tubes. The depth of the rack should be at least 45 inches deep, so that the complete round is contained within the rack. Spacing between tiers (vertical) must be at least 10 inches. Steel spacers must be positioned as in Figure 1, with separations of 6 inches, center to center, alternating with spacings of 3 inches, center to center. The support rods on 3 inch centers locate the shipping tubes with respect to each other. On the top of the rack, angle iron or rebar roof supports may be welded in place, as in Figure 1. A sheet of corrugated steel or fiberglass can be used as a rain cover and as a support for the sand cover. A sand cover of one sand bag thickness or 6 inches of loose sand is adequate for fragment protection. Note that cinder blocks, bricks, and concrete blocks are not acceptable for this application, as they serve as a source of secondary hazardous fragments. Sides of the structure are to be barricaded with a minimum of 6 inches of sand (one sandbag thickness), with the barrier joining the roof in such a way that continuous fragment protection is provided. If a natural barricade such as a berm or bank is not located behind the rack, then a sand barrier at least 3 feet thick will be placed behind the rack. The barricade may be placed in contact with the rack or it may be placed an arbitrary distance from the rack. If access to the rear of the rack is desired, a walkway space of at least 32 inches between the rack and rear barrier should be provided. In front of the rack, a barricade of sandbags (6 inches thick), cinder blocks, railroad ties, or other materials must be erected to provide protection from kickouts. The distance of this barricade from the front of the rack may be chosen for operational convenience. The minimum height of both the front and rear barricades must be equal to the top of the rack. An additional foot of height is required for both front and rear barricades for each yard of separation. Breadth of the rack is unlimited. topmost tier of rounds shall not be more than 79 inches center of the round to ground to insure standing functional reach. This results in a round to round surface separation of 3 inches, which is sufficient to prevent round to round propagation of detonation. Significant deviations in design require approval by the DOD Explosives Safety Board. The rack, with sand covers and side barriers in place, is shown in Figure 2a. Several collocated racks are shown in Figure 2b. Note that the hazard radii are still 50 feet for the larger configuration.

V. USE OF THE RACK

The rack may be used to provide temporary storage of 105 mm tank ammunition, provided the rack is configured as described above, the ammunition is stored in the original shipping tubes, and the tubes are placed in the racks such that the warheads face towards the rear of the rack, provided the rack is located in excess of 50 feet from the nearest inhabited building, and provided express approval for siting is obtained from the DOD Explosives Safety Board.



ACKNOWLEDGEMENTS

This work was sponsored by the DOD Explosives Safety Board. The final rack design was engineered by members of the US Army Human Engineering Laboratory's HELFAST Team, led by Mr. John D. Waugh. The shop drawing was prepared by members of the Engineering Design Division, USAHEL.




Figure 1. Rack




Figure 2. (a) Rack with Sand Covers and Side Barriers in Place.
(b) Several Collocated Racks.

DISTRIBUTION LIST

No. of Copies Organization

- 12 Administrator
 Defense Technical Info Center
 ATTN: DTIC-DDA
 Cameron Station
 Alexandria, VA 22314
 - 1 HQDA DAMA-ART-M Washington, DC 20310
- 5 Chairman
 DOD Explosives Safety Board
 ATTN: Dr. T. Zaker
 COL O. Westry
 Room 856-C
 Hoffman Bldg 1
 2461 Eisenhower Avenue
 Alexandria, VA 22331
- 1 Under Secretary of Defense for Research & Engineering Department of Defense Washington, DC 20301
- 1 Assistant Secretary of Defense (MRA+L) ATTN: EO&SP Washington, DC 20301
- 1 Chief of Research, Development, & Acquisition Department of the Army ATTN: DAMA-CMS-CA, Mr. Lippi Washington, DC 20310
- 1 HQDA (DAMO-NC) ATTN: COL R. D. Orton Washington, DC 20310
- 1 HQDA (DCSLOG) ATTN: Elliot Seard Room 1D563, Pentagon Washington, DC 20310

No. of Copies Organization

- 2 Assistant Secretary of Army (I&L)
 Department of the Army
 ATTN: Lewis D. Walker
 John Nash
 Room 3E606, Pentagon
 Washington, DC 20310
- 1 Commander
 USA Safety Center
 ATTN: PESC-Z
 Fort Rucker, AL 36360
- 1 Commander
 US Army Materiel Command
 ATTN: AMCDRA-ST
 5001 Eisenhower Avenue
 Alexandria, VA 22333-0001
- 1 Commander US Army Materiel Command ATTN: AMCSF 5001 Eisenhower Avenue Alexandria, VA 22333
- 1 Director
 AMC Field Safety Activity
 Charlestown, IN 47111
- 1 HQDA (DAPE-HRS) Washington, DC 20310
- 1 Commander
 Armament R&D Center
 US Army AMCCOM
 ATTN: SMCAR-TDC
 Dover, NJ 07801
- 1 Commander
 Armament R&D Center
 US Army AMCCOM
 ATTN: SMCAR-TSS
 Dover, NJ 07801
- 1 Commander
 Armament R&D Center
 US Army AMCCOM
 ATTN: SMCAR-LCM-SP
 Dover, NJ 07801

DISTRIBUTION LIST

No. of Organization

- 1 Commander
 Armament R&D Center
 US Army AMCCOM
 ATTN: SMCAR-IL
 Dover, NJ 07801
- 1 Commander
 US Army Armament, Munitions
 and Chemical Command
 ATTN: SMCAR-ESP-L
 Rock Island, IL 61299
- 1 Commander
 US Army Armament, Munitions
 and Chemical Command
 ATTN: SMCAR-SF
 Rock Island, IL 61299
- 1 Commander
 US Army Aviation Research
 and Development Command
 ATTN: AMSAV-E
 4300 Goodfellow Boulevard
 St. Louis, MO 63120
- 1 Director
 Benet Weapons Laboratory
 Armament R&D Center
 US Army AMCCOM
 ATTN: SMCAR-LCB-TL
 Watervliet, NY 12189
- 1 Director US Army Air Mobility Resarch and Development Laboratory Ames Research Center Moffett Field, CA 94035
- 1 Commander
 US Army CommunicationsElectronics Command
 ATTN: AMSEL-ED
 Fort Monmouth, NJ 07703

No. of Copies Organization

- 1 Commander
 US Army Electronics Research
 and Development Command
 Technical Support Activity
 ATTN: DELSD-L
 Fort Monmouth, NJ 07703-5301
- 1 Commander
 US Army Missile Command
 ATTN: AMSMI-R
 Redstone arsenal, AL 35898
- 1 Commander
 US Army Missile Command
 ATTN: AMSMI-YDL
 Redstone arsenal, AL 35898
- 1 Commandant US Army Missile Munitions Center & School Redstone Arsenal, AL 35897
- 1 Commander
 US Army Tank Automotive Command
 ATTN: AMSTA-TSL
 Warren, MI 48090
- 1 Director
 US Army TRADOC Systems
 Analysis Activity
 ATTN: ATAA-SL
 White Sands Missile Range,
 NM 88002
- 2 Project Manager
 Ammunition Logistics
 ATTN: COL P. Greenberg
 Mr. G. Goble
 Dover, NJ 07801
- 1 Commandant
 US Army Infantry School
 ATTN: ATSH-CD-CSO-OR
 Fort Benning, GA 31905



DISTRIBUTION LIST

No. of Copies Organization

- 1 Commander US Army Defense Ammo Center & School ATTN: John Byrd Savanna, IL 61074
- 1 Commander
 US Army Development & Employment
 Agency
 ATTN: MODE-TED-SAB
 Fort Lewis, WA 98433
- 1 HQ, 8th US Army ATTN: DJ-AM-SS (McDowell) APO San Francisco 96301
- 1 Commander US Army Europe ATTN: Chief of Staff APO New York, NY 09403
- 1 Commander US Army Europe ATTN: AEAGA-SE APO New York, NY 09403
- 1 Commander US Army Europe ATTN: G-4 APO New York, NY 09403
- 1 Commander
 Naval Sea Systems Command
 ATTN: Mr. R. Beauregard,
 SEA 64E
 Washington, DC 20362
- 1 Commander Naval Explosive Ordnance Disposal Facility ATTN: Technical Library, Code 604 Indian Head, MD 20640
- 1 Commander Naval Surface Weapons Center ATTN: J. Ward, R15 Silver Spring, MD 20910

No. of Organization

- 1 Commander
 Fleet Marine Force, Atlantic
 ATTN: G-4 (NSAP)
 Norfolk, VA 23511
- Air Force Armament Laboratory ATTN: AFATL/DLODL Eglin AFB, FL 32542-5000
- 1 AFWL/SUL Kirtland AFB, NM 87117

Aberdeen Proving Ground

Dir, USAMSAA
ATTN: AMXSY-D
AMXSY-MP, H. Cohen
AMXSY-R, R. Simmons
Cdr, USATECOM
ATTN: AMSTE-TO-F
Cdr, USAHEL
ATTN: Jack Waugh
Cdr, CRDC, AMCCOM

ATTN: SMCCR-RSP-A SMCCR-MU SMCCR-SPS-IL

USER EVALUATION SHEET/CHANGE OF ADDRESS

This Laboratory reports it publ aid us in our e	undertakes a continuing effort t ishes. Your comments/answers to fforts.	o improve the quality of the the items/questions below will
1. BRL Report	Number	Date of Report
2. Date Report	Received	
3. Does this r other area of i	eport satisfy a need? (Comment o	n purpose, related project, or be used.)
4. How specifi data, procedure	cally, is the report being used?	(Information source, design
		
as man-hours or	ormation in this report led to an dollars saved, operating costs a ease elaborate.	y quantitative savings as far voided or efficiencies achieved
6. General Comreports? (Indi	ments. What do you think should locate changes to organization, tecl	be changed to improve future hnical content, format, etc.)
Na	ame	· · · · · · · · · · · · · · · · · · ·
CURRENT Or	rganization	
ADDRESS \overline{AG}	ddress	
C	ity, State, Zip	
7. If indicating New or Correct A	g a Change of Address or Address oddress of ddress in Block 6 above and the O	Correction, please provide the ld or Incorrect address below.
\overline{N}	ame	

(Remove this sheet along the perforation, fold as indicated, staple or tape closed, and mail.)

OLD

ADDRESS

Organization

City, State, Zip

Address

- FOLD HERE -

Director

US Army Ballistic Research Laboratory

ATTN: AMXBR-OD-ST

Aberdeen Proving Ground, MD 21005-5066



OFFICIAL BUSINESS

PENALTY FOR PRIVATE USE, \$300

BUSINESS REPLY MAIL

FIRST CLASS PERMIT NO 12062 WASHINGTON, DC

POSTAGE WILL BE PAID BY DEPARTMENT OF THE ARMY

Director
US Army Ballistic Research Laboratory
ATTN: AMXBR-OD-ST
Aberdeen Proving Ground, MD 21005-9989

NO POSTAGE
NECESSARY
IF MAILED
IN THE
UNITED STATES



	,				
				•	